

# Easy to machine



**Graphite is produced in the form of blocks: rectangular, round or cylindrical or crucible form. It is often demanded that the final product be in the form of a particular shape. In order to produce the shape to the required dimensions the blocks should be cut to a rough shape and then finally machined. Graphite easily lends itself to such cutting and machining operations.**